GEORGE LOMBARD JR.

2024 Bowman Chrome | 1st Bowman | #BCP-79 | New York Yankees

SAI-2026-GL-1024-001 | Finalized October 24, 2026

10 GEM MINT

Photo-based condition estimate | Moderate review confidence

CENTERING

Front borders appear reasonably balanced, with no obvious major shift on the reverse. Camera perspective prevents a calibrated centering measurement.

CORNERS

The visible front corners appear sharp, with no obvious bends or substantial rounding. Fine reverse-corner detail is limited to one overall photograph.

EDGES

Edges look generally clean. Possible minor top-edge roughness is visible in IMG_2546; the photographs do not establish definite chipping.

SURFACE

The owner reports the card is clean after in-hand inspection. A pale spot on the lower-right blue border appears in IMG_2544, IMG_2547, and IMG_2548, with faint pale marks near the Chrome logo and scattered specks. Their cause remains unresolved in the photos; no definite scratch, crease, or dent is established.

REVIEW BASIS

Eight submitted photos were reviewed. The finalized 10 Gem Mint photo estimate incorporates the owner's report that the card is clean. The blue-border spot and possible top-edge roughness remain unresolved in the images. This is an estimated condition opinion, not a confirmed in-hand grade; no measured subgrades were assigned.

https://gradingwithai.com/cert/SAI-2026-GL-1024-001

This certificate records a photo-based condition estimate and identifies the card shown in the submitted images. It does not establish physical authenticity or guarantee another grader's result. Hidden defects or alterations may require in-hand inspection.

Labels: 2.52 x 0.78 inches each. Print at Actual Size / 100%.

COMPLETE SUBMITTED PHOTO RECORD

SAI-2026-GL-1024-001 | All 8 originals preserved on the certificate




01 Front overview




02 Front upper-right corner



03 Front lower-right corner and blue-border detail



04 Front lower-left corner and Chrome logo detail




05 Front upper-left corner and top-edge detail



06 Angled front overview



07 Additional angled front overview



08 Card reverse